



Technical Bulletin

Part No AA6272, AA6276

Vehicles Affected: Vauxhall Astra, Vectra & Zafira

Before replacing the alternator check the pulley on the unit removed from the vehicle, if the pulley is either

Seized, turning without the Alternator turning, broken up or completely missing, this will

Point towards another fault on the vehicle which has caused the pulley to fail

You must check the automatic drive belt tensioner and ensure that the belt has been correctly fitted before replacing the alternator

Failure to check these components may result in the new alternator failing prematurely

Autocharge UK Ltd
Unit 3 Whitehall Court, Whitehall Park, Farnley, Leeds, West Yorkshire, LS12 5SN
Tel 0113 2794210
Fax 0113 2632111
Email sales@autochargeuk.co.uk
Web www.autochargeuk.co.uk