

# Technical Bulletin

Part No AA6862

Vehicles Affected: Jeep Cherokee 3.7,4.8 2001-2007

## Correct Diagnosis

Unlike on most modern vehicles the charging system fitted to the Jeep Cherokee 3.7 & 4.7 petrol has an external voltage regulator

When this fails the result is no charge

Replacing the alternator will not fix the problem if the regulator has failed

Before replacing the alternator locate and test the external regulator

**If mis-diagnosed once fitted this unit cannot be returned for credit**