



Technical Bulletin

Part Nos: AA5000,5071,5011,5073,5547,5005,5052,5409

Vehicles Affected: Various Ford Models

There is an inherent fault on Ford vehicles which often leads to misdiagnosis of the alternator

There is often a small break in the wiring loom which runs from the back of the alternator causing no charge and the battery light to illuminate on the dashboard.

Before replacing the alternator test for this fault and replace the wiring as the alternator may not be at fault

If misdiagnosed once fitted this unit cannot be returned for credit

Autocharge UK Ltd
Unit 3 Whitehall Court, Whitehall Park, Farnley, Leeds, West Yorkshire, LS12 5SN
Tel 0113 2794210
Fax 0113 2632111
Email sales@autochargeuk.co.uk
Web www.autochargeuk.co.uk