



Technical Bulletin

Part Numbers AA6343 & AA7512 Smart Fortwo CDi 2007>

There are 2 different alternators fitted to the above vehicle. Both units look identical however the internal regulators are different meaning these units do not interchange.

AA6343 has L & DFM Terminals

AA7512 has COM & LIN2 Terminals

If you are in doubt please obtain the Bosch or Mercedes number from the customer`s unit and enter this into the cross reference option the website, this will take you to the correct Autocharge number.