



# Technical Bulletin

**Part No AA6603**

**Vehicles Affected: Chrysler PT Cruiser 2.0 Petrol**

## Correct Diagnosis

Unlike on most modern vehicles the charging system fitted to the PT Cruiser 2.0 petrol has an external voltage regulator

When this fails the result is no charge

Replacing the alternator will not fix the problem if the regulator has failed

Before replacing the alternator locate and test the external regulator

**If mis-diagnosed once fitted this unit cannot be returned for credit**

Autocharge UK Ltd  
Unit 3 Whitehall Court, Whitehall Park, Farnley, Leeds, West Yorkshire, LS12 5SN  
Tel 0113 2794210  
Fax 0113 2632111  
Email [sales@autochargeuk.co.uk](mailto:sales@autochargeuk.co.uk)  
Web [www.autochargeuk.co.uk](http://www.autochargeuk.co.uk)