



Technical Bulletin

Part No AS1216

Vehicles Affected: Nissan Micra K12

There is an inherent fault on the Nissan Micra K12 where the ignition switch sticks on causing the starter motor to remain spinning even when the key has been released

This leads to premature failure of the starter motor

Before replacing the starter motor check for a sticking switch or visible signs of damage to the teeth on the drive

Warranty claims for units with damaged teeth caused by a sticking switch will not be accepted for credit

Autocharge UK Ltd
Unit 3 Whitehall Court, Whitehall Park, Farnley, Leeds, West Yorkshire, LS12 5SN
Tel 0113 2794210
Fax 0113 2632111
Email sales@autochargeuk.co.uk
Web www.autochargeuk.co.uk