



# Technical Bulletin

**Part No's AA6387 & AA6936**

**Vehicles Affected: Toyota Auris 2006-2009**

**Fitted with the 1.6 1ZR-FE engine**

**This vehicle was manufactured at production plants in the UK & Japan, and each plant used a different alternator**


**Despite the fact they both look identical, fitting the wrong unit will result in a none charge and possible costly ECU damage**

**Ensure you supply the correct unit!**

**Chassis no starts SB1 for UK models – AA6936**

**Chassis no starts JT1 for Japanese Models – AA6387**

**SB1KV56E00F055527**



**SB1 – UK  
Built Model**

Autocharge UK Ltd  
Unit 3 Whitehall Court, Whitehall Park, Farnley, Leeds, West Yorkshire, LS12 5SN  
Tel 0113 2794210  
Fax 0113 2632111  
Email [sales@autochargeuk.co.uk](mailto:sales@autochargeuk.co.uk)  
Web [www.autochargeuk.co.uk](http://www.autochargeuk.co.uk)