



Technical Bulletin

Part No's AA5556 & AA7352


**Vehicles Affected: Subaru Forester, Impreza & Legacy
1.6, 2.0, 2.5**

Care needs to be taken when supplying an alternator for the above vehicles, although the mentioned part numbers look identical they are not.


AA7352 Has a computer (ECU) terminal, AA5556 doesn't

The images below show the 2 differences as does our catalogue data

AA5556



AA7352



Ensure you supply the correct unit as claims for Incorrectly supplied units will not be accepted

Autocharge UK Ltd
Unit 3 Whitehall Court, Whitehall Park, Farnley, Leeds, West Yorkshire, LS12 5SN
Tel 0113 2794210
Fax 0113 2632111
Email sales@autochargeuk.co.uk
Web www.autochargeuk.co.uk