



Technical Bulletin

Part No AS1206

Vehicles Affected: Citroen C1, Peugeot 107, Toyota Aygo

Fitted with the 1.0 1KR-FE engine

Several aftermarket non OEM versions of this popular unit are fitted with the wrong nose-cone resulting in excessive noise during operation

Our AS1206 is supplied as a new OEM to overcome this problem

Autocharge UK Ltd
Unit 3 Whitehall Court, Whitehall Park, Farnley, Leeds, West Yorkshire, LS12 5SN
Tel 0113 2794210
Fax 0113 2632111
Email sales@autochargeuk.co.uk
Web www.autochargeuk.co.uk